

Task No.	Task Description	Hazards	Risk Assessment	Control Measures	PPE Required	Responsible Person	Emergency Procedures	Training Required	Sign-Off
1	Site Setup	Tripping hazards from equipment	Medium	Clear workspace, use warning signs	High-visibility vest, gloves	Site Supervisor	First aid kit on site, emergency contacts	Induction training on site setup	[Signature]
2	Equipment Inspection	Equipment failure	High	Inspect pressure washer before use, check hoses for damage	Gloves, safety glasses	Technician	Disconnect power, report to supervisor	Equipment handling training	[Signature]
3	Pressure Cleaning	Electrical hazards, slips, noise	High	Use GFCI outlets, ensure non-slip surfaces, limit noise exposure	Gloves, safety boots, hearing protection	Operator	Shut off equipment, evacuate area	Electrical safety training	[Signature]
4	Post-Cleaning Inspection	Residual water causing slips	Medium	Ensure area is dry, remove excess water	Gloves, safety boots	Site Supervisor	N/A	N/A	[Signature]
5	Site Cleanup	Waste disposal issues	Low	Properly dispose of wastewater and debris	Gloves	All Staff	Follow local disposal regulations	Waste handling procedures	[Signature]